2000 0578

FILED RECORDERS OFFICE JONES COUNTY IOWA

00 FEB 17 AM II: 05

MARIE KRUTZFIELD.
RECORDER 6.000

Rome

CLARENCE J. WALTON, BRAIN ENGINEERING, INC., 777 10TH STREET, MARION, IOWA 52302 PH. (319) 373-1318

STATES PUBLIC UNITED SURVEY CORNER CERTIFICATE LAND SURVEY MONUMENTS SITUATED IN SECTION 6 ___, TOWNSHIP _83_ NORTH ____ COUNTY, IOWA. RANGE _3_ WEST OF THE 5TH P.M., ____JONES_____ NO SCALE NO SCALE N 1/4 CENTER FOUND "X" NAILS IN POWER POLE SET "X" NAILS IN POWER POLE 65.60 69.91 GREEN ROAD SET "X 0.28 29.57 NAILS IN .93 POST 18.38 37.73 FOUND SCM FOUND "X"
NAILS IN
GATE POST SET "X" SET NAILS "X" NAILS IN FENCE CORNER SET "X" NAILS IN POST PREVIOUSLY RECORDED IN BOOK 341 PAGE 46 PREVIOUSLY RECORDED IN BOOK _____ PAGE ____ MONUMENT DESCRIPTION AND HOW ESTABLISHED __ MONUMENT DESCRIPTION AND HOW ESTABLISHED __ FOUND SCM 2" ABOVE GROUND. FOUND 1/2" REBAR CORNERS TO BE INDEXED I hereby certify that this land surveying document and the related survey work was performed by me or under my direct personal supervision and that I am a duly licensed Land Surveyor under the laws of the State of lawa.

Date

Land Walls Care 2/16/80 CORNER SECTION **TOWNSHIP** RANGE LAND N 1/4 6 T8.3N R.3W CENTER 6 **T83N** R3W CLARENCE BRAIN ENGINEERING. J. WALTON Clarence J. Walton, L.S.
My License Renewal Date Is December 31, 2001
License Number 11310
Pages or sheets covered by this seal: 777 10TH STREET MARION, IOWA 52302 25189-10 AWOI (319) 373-1318

SECTION CORNER CERTIFICATE
LAND SURVEY MONUMENTS SITUATED IN SECTION 6, TOWNSHIP 83 NORTH, RANGE 3 WEST, OF THE FIFTH PRINCIPAL MERIDIAN, JONES, COUNTY, IOWA.
PREVIOUSLY RECORDED IN BOOK AT PAGE FOR RECORDER'S USE
REASON FOR PREPARING CERTIFICATE: A) THERE IS NO CERTIFICATE FOR THE CORNER ON FILE WITH THE RECORDER OF THE COUNTY IN WHICH THE CORNER IS LOCATED. B) CORNER POSITION DIFFERS FROM THAT SHOWN IN THE PUBLIC RECORDS OF THE COUNTY IN WHICH THE CORNER.IS LOCATED. C) THE CORNER MONUMENT HAS BEEN REPLACED OR MODIFIED. D) THE REFERENCE TIES REFERRED TO IN AN EXISTING PUBLIC RECORD ARE INCORRECT.
MONUMENT DESCRIPTION AND REMARKS: NW CORNER - SE'4 SECTION 6-T83N-R3W SET 'z" REBAR W/ L.S. CAP # 8165 ON & EXTENDED OF SCIDE ROCK ROAD \$ ON SOUTH EdgE OF GREEN ROAD SHOULDER SW CORNER - NW'4-SE'4 SECTION 6-T83N-R3W SET 'z" REBAR W/ L.S. CAP # 8165 FLUSH 6' SOUTH \$ 4'z' EAST OF FENCES
RECOVERY TIE DRAWING
N.W.Cor S.E. 4 6-83-3
GREEN WY CAP WY CAP WY CAP TO ST TO ST
I, GLEN D. MEISNER,-CERTIFY THAT THE CORNER LOCATION(S) SHOWN ON THIS RECORD WERE DETERMINED BY ME OR UNDER MY DIRECTION AND CONTROL AND THAT THIS U.S. PUBLIC LAND SURVEY MONUMENT RECORD IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF. 6-29-93 GLEN D. MEISNER L.S. NO 8165 DATE
L A COVERNMENT CORNER O 5/8" THE PIN SET O CENTERLINE CONTERLINE ROW, LINE U.S. PUBLIC LAND SURVEY RECORD HALL AND HALL ENGINEERS, INC. 226 29TH STREET DRIVE S.E. CEDAR RAPIDS, IOWA 52403 319-362-9548
RWB GDM 3-29.93 NONE OT 26 9 4833