UNITED STATES PUBLIC LAND SURVEY CORNER CERTIFICATE SLSI 9-90

OF

Land Survey Monuments situa	ted in Section3	6 , Township 86	N, Range County, Iowa.
Previously recorded in	<u> </u>	in Co	inty Recorder's Office.
Show reason for preparing this certification found or placed.) Monument Description and Re			corner positions and monu-
NE Corner NW1/4 -	Set 1/2" Iron Pin		
NE Corner SW1/4 -	Found Limestone	Set 1/2" Rebar	
NE Corner SW1/4 -	Set 1/2" from Pin		
	PLAN - V		
Show a minimum of three reference ecovery of the corner.)	ties to durable physical objects, re	elevant monuments and physical co	onditions that will enable
		L.	
	10 cedar		
(Tree 9		
N.W. Cor		5"Oak	
Section 36 g	•	() Tree	Section 36
\ a\o'		42 . A	1
Buer 81.85 47.8	24"Hord of Maple	مذ	
\$ 5463	()	KTHER OF	
	The state of the s	72.35	Y
*		18"	
		Corner 18 Hickory	•
	NW	14 sec. 36 Tree	N '
* WC	P		1,
	1 36" P Oak	And the state of t	e la companya de la companya del companya de la companya del companya de la compa
امر	V 1		
\(\frac{\partial}{\partial}\)	5°	W.P. 3rdw.P.	CP
18"Oak X 4"	for the second section -		
37.70'		63.35.	O_{\bullet}
	NE COR	37	Dennis
1	Sec 36	(NE Corner	>/30/9/
	Ed. Stone	SW 1/4 Sec. 36	7750797
	The second secon		

hereby certify that the survey work was completed and this certificate	List Corners to be Indexed			
was prepared by me or under my direct personal supervision and that I am a duly registered land surveyor under the laws of the state of	Corners	Section	Twp	Range
Signature: Have T- Crawford	NWComer	36	86 N	1 W
Name typed or printed: Daniel 1. Crawford, R.L.S. Date: 4/18/91 Reg. No. 8812	NE Corner NW 1/4	3 6	86 N	I W
LAND SEN	NE Corner	36	E6N	I W
SEAL DANIEL T. CRAWFORD SEAL 8812	NECorner SW 1/4	36	86 N	" IW
0012				
10WB				i .