


UNITED STATES PUBLIC SECTION CORNER CERTIFICATION
AND LAND CORNER SURVEY
SECTION 8 T-85N R-3W

MADE FOR
IOWA DEPARTMENT OF TRANSPORTATION FOR THE PURPOSE OF
RIGHT OF WAY DESCRIPTIONS ON PRIMARY ROAD No. U.S. 151

MADE BY
MICHAEL R. FAGLE R.L.S. No. 8505
JONES COUNTY, IOWA NHS-151-3(84)--19-57
APRIL 1998 THRU OCTOBER 1998












ALL DISTANCES WERE CAREFULLY MEASURED AND MAY NOT AGREE WITH ROAD SURVEY STATIONING



	<p>I hereby certify that this Land Surveying document was prepared by me or under my direct personal supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Iowa.</p> <p><i>Michael R. Fagle</i> 1-21-99 MICHAEL R. FAGLE Date</p>
	<p>License number 8505 My license renewal date is December 31, 2000 Pages or sheets covered by this seal: <u>Two (2)</u></p>

METRIC

UNITED STATES PUBLIC SECTION CORNER CERTIFICATION
 AND LAND CORNER SURVEY
 SECTION 8 T-85N R-3W



ALL TIES ARE ENGLISH UNLESS OTHERWISE NOTED

JONES COUNTY, IOWA
 U.S. PUBLIC LAND SURVEY CORNER CERTIFICATE
 Sec. 8 T 85 N R 3 W
 West Quarter (W¹/₄) Corner

*Wayne
E¹/₄ Sec. 7*

1. TYPE OF MONUMENT
 (check one)

- Section Corner Bench Mark
 Quarter Corner Other _____

2. REASON FOR PREPARATION OF
 CERTIFICATE

- There is no certificate for the corner on file with the County Recorder.
 The corner position differs from that shown in the public records of the county.
 The corner monument has been replaced or modified.
 The reference ties referred to in an existing public record are not correct.


3. DESCRIPTION OF EVIDENCE FOUND AND
 DETAILED PROCEDURES USED IN
 ESTABLISHING THE CORNER POSITION.

Found 5/8" iron rod. Concrete monuments also found at NW 1/4 and N 1/4 Corners from IDOT ties. Iron rod position matches IDOT corner survey data.

4. DESCRIPTION OF MONUMENT AND/OR
 ACCESSORIES TO PERPETUATE THE
 LOCATION OF THIS POINT.

Found 5/8 inch Iron Rod at corner, no RLS cap. See Plan-view for accessories.

5. PLAN-VIEW SITE DRAWING SHOWING
 RELATIVE LOCATION OF MONUMENT,
 PHYSICAL SURROUNDINGS AND REFERENCE
 TIES.




*ON Card
8-17-90
R.P.*

DATE OF FIELD WORK 7-12-90

I hereby certify that this plat, map, survey or report was made by me or under my direct personal supervision, and that I am a duly Registered Land Surveyor under the laws of the state of Iowa.

Roger R. Mohn
 Roger R. Mohn



Date 7-12-90 Reg. No. 10165

SHEET 1 OF 1

853070-071290